## POPPLETON HISTORIC STUDY

Block

200

Lot

Address

98-101/103 1034-1040 W. Fairmount Avenue

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

1040

1034-1038


Rating	Rating Architectural		Condition		
A	Significant-save	good	fair	poor	bad
В	Quality-Indiv./groups-save	good	fair	poor	bad
CC	Important to street/groups	good	fair	poor	bad
	Insignificant/detrimental	good	fair	poor	bad


## Notable features:

Numbers 1034-1038 are 2-story flat houses with cellar entrances. There is a sallyport between 1038 and 1040. Number 1040 is a 2-story gable with segmental window arches. Numbers 1034 and 1036 have been formstoned.

## Environmental context:

Numbers 1034 and 1036 are vacant. The group is adjacent to the former site of the iron works and saw mill. A junkyard remains opposite on the former site of the old marble works, where a hoist and other remnants of the works can still be seen. Surrounded by cleared or open land, these houses are so isolated and disconnected that their fate depends entirely on a redesign for this block.





**Demolished** 

B-2567 1034-1040 W. Fairmount Avenue Block 0200, Lots 98-101/103 Baltimore West Over 1

